BK Mikro Trace Function

From BK Mikro software startup screen select BK-Mikro9→Manual Mode→Trace tab

Select: Start Trace \rightarrow Give it a file name. This will normally default to saving the file in C:\Program Files (x86)\BK Mikro9\System Setup BK Mikro9 QT\trace. You can select another folder if you'd like. (If it won't let you run a trace try reopening software as an administrator. To do this close the software and reopen it by right clicking and selecting Run as Administrator.)

Select Tracefile ×	
← → ∽ ↑	
Organize New folder Image: Counter Limit Out1 Function Out2 Function Out3 Funct VPN Name Date modified Type Size Size 0 0K NotDefined Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Out1 Function Out3 Function Out3 Function Image: Line counter Limit Name Date modified Type Size Size Image: Line counter Limit Image: Line counter Limit Out1 Function Out3 Function Out3 Function Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Out1 Function Out3 Function Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Out1 Function Out3 Function Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Out1 Function Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Limit Image: Line counter Lim	
VPN Name Date modified Type Size United Type Size 2084 0 OK KO NotDefined Type Size 2084 0 OK KO NOTDEFINE SIZE 2084 0 OK	on Out
Website & Brochure Inc 8/5/2021 10:29 AM TRC File Techna-Tool Inc 8/5/2021 10:59 AM TRC File	
Intrc 8/5/2021 10:29 AM IRC File Intrc 8/5/2021 10:59 AM TRC File	
lechna-lool	
Tree State Tree Site - Tree Si	
line PC	
30 Objects	
Description	
Downloads	
Music	
Pictures	
📓 Videos	
Windows (C:)	
File name. Skiller Skille	
Quen Cancel	
	►
Cyclic Mode Current Function No FuncNo MeasuredPos ObjectPos Status	
Functio 0	
Teach Mode CheckObj	
Start Kötene	
ObjectPos 113.00	
Stop TeachLimit 270.00	
Tolerance 10.00	
Intensity Ultra Low	
Stop Trace Counter Limit 0	
I race not active!	
B: In:	
1]]]	

Each time the controller gets a start signal or teach input it will popluate another entry in the area where the yellow box is in the photo on page 2. You can look at data here or open the file in excel, work or notepad to view the data.

No= The number of checks it has recorded

FuncNo= Is the Function number. For basic controllers it will normally be 0 for Premium it will equal the tool number you're checking.

MeasuredPos= The angle it actually checked. If it's less than the ObjectPos it stopped before hitting the object, if it's greater than it went past or missed the object.

ObjectPos= Is the stored position from the last teach/learn cycle

Status= OK if the check was good or KO if the check was bad and outside of the tollerance area it should be checking in. (If the status is -- that is usually show during a teach cycle)

If you want it to continuously check you can check mark the Cyclic Mode box then press the start button. It will repeatedly check the over and over. If you want it to stop on a fault check the Stop On KO box.

		ual Mode													- 0	
nual	Trace	Error Buffer]													
uncNo	Name		Mode	BackMode	NextFunc	KOFunc	ObjectPos	TeachLimit	Tolerance	Intensity	Counter	Counter Limit	Out1 Function	Out2 Function	Out3 Function	n O
00			CheckObi				105.00	270.00	10.00	Ultra Low	2124	0	ок	ко	NotDefined	-
1																
Cydi	ic Mode		wont fun -**						_	No	FuncNo	MeasuredPos	ObjectPos	Statu	s	
Cydi	c Mode On KO	Cur	rent Functi	DN		0			_	No	FuncNo	MeasuredPos	ObjectPos	Statu: OK	s	
Cydi	c Mode On KO	Cur Fun	rent Functi cNo	DN		0 Charlobi				No 90 97	FuncNo 0	MeasuredPos 105.00 105.00	ObjectPos 105.00 105.00	Statu UK OK	S	
Cydi Stop Delay	c Mode On KO	Cur Fun Moc	rent Functi cNo le	on		0 CheckObj				No 90 97 98	FuncNo 0 0	MeasuredPos 105.00 105.00	ObjectPos 105.00 105.00 105.00	Statu OK OK	5	
✓ Cycli Stop Delay	c Mode On KO	Cur Fun Moo Nex	rent Functi cNo de tFunc	on		0 CheckObj				No 90 97 98 99	FuncNo 0 0 0	MeasuredPos 105.00 105.00 105.00 105.00	ObjectPos 105.00 105.00 105.00 105.00	Statu OK OK OK	5	
Cydi Stop Delay	c Mode On KO each	Cur Fun Moo Nex KOF	rent Functi cNo de tFunc unc	on		0 CheckObj				No 90 97 98 99 100	FuncNo 0 0 0 0 0	MeasuredPos 105.00 105.00 105.00 105.00 105.00	ObjectPos 105.00 105.00 105.00 105.00 105.00	OK OK OK OK OK OK	5	
Cycli Stop Delay	ic Mode On KO jeach	Cur Fun Moc Nex KOF Obje	rent Functi cNo le tFunc unc ectPos	on		0 CheckObj 105.00				No 90 97 98 99 100 101	FuncNo 0 0 0 0 0 0 0	MeasuredPos 105.00 105.00 105.00 105.00 105.00 73.00	ObjectPos 105.00 105.00 105.00 105.00 105.00 105.00 105.00	OK OK OK OK OK OK	\$	
✓ Cydi Stop Delay	c Mode On KO jeach	Cur Fun Moc Nex KOF Obju Tea	rent Functi cNo le tFunc unc ectPos chLimit	Dn		0 CheckObj 105.00 270.00				No 90 97 98 99 100 101 102 102	FuncNo 0 0 0 0 0 0 0 0 0 0	MeasuredPos 105.00 105.00 105.00 105.00 105.00 105.00 73.80 73.80	ObjectPos 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00	Statu OK OK OK OK OK OK	\$	
✓ Cydi Stop Delay	c Mode On KO jeach Start Stop	Cur Fun Moc Nex KOF Obj Tea Tok	rent Functi cNo le tFunc unc ectPos chLimit erance	on		0 CheckObj 105.00 270.00 10.00				No 97 98 99 100 101 102 103	FuncNo 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	MeasuredPos 105.00 105.00 105.00 105.00 105.00 73.80 105.00 105.00	ObjectPos 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00	Statu OK OK OK OK OK KO OK	\$	
Cycli Stop Delay	c Mode On KO each Start Stop	Curri Fun Moc Nex KOF Obj Tea Tole	rent Functi cHo je tFunc unc ectPos cctDos chLimit erance ensity	on		0 CheckObj 105.00 270.00 10.00 Ultra Low				No 90 97 98 99 100 101 102 103 104	FuncNo 0	MeasuredPos 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00	ObjectPos 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00	Statu OK OK OK OK OK KO OK OK	5	
Cydl Stop Delay	c Mode On KO each Stop	Cur Fun Moc Nex KOF Obj Tea Tole Tole	rent Functi cNo le tFunc unc ectPos chLimit erance ensity unter	Dn		0 CheckObj 105.00 270.00 Ultra Low 2124				No 90 97 98 99 100 101 102 103 104 105	FuncNo 0 0 0 0 0 0 0 0 0 0 0 0 0	MeasuredPos 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00 105.00	ObjectPos 105:00 105:00 105:00 105:00 105:00 105:00 105:00 105:00 105:00	OK OK OK OK OK OK OK OK OK	5	
Cydl Stop Delay I Star Stor	c Mode On KO each Start Stop rt Trace	Cur Fun Moc Obj Tea Tole Inte Cou Cou	rent Functi cHo je tFunc unc ectPos chLimit erance ensity inter inter Limit	Dn		0 CheckObj 105.00 270.00 10.00 Ultra Low 2124 0				No 90 97 98 99 100 101 102 103 104 105 106 Trace-File: 1	FuncNo 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	MeasuredPos 105:00 105:00 105:00 105:00 105:00 105:00 105:00 105:00 105:00	ObjectPos 105:00 105:00 105:00 105:00 105:00 105:00 105:00 105:00 105:00	Statu VK VK OK OK OK	5	